FIG.1 (PRIOR ART)




FIG.2 (PRIOR ART)




FIG.3
(PRIOR ART)





FIG.4 (PRIOR ART)



3 / 15

FIG.5




FIG.6




FIG.7




FIG.8




FIG.9




FIG.10




FIG.11




FIG.12




FIG.13




FIG.14




FIG.15




FIG.16




FIG.17




FIG. 18




FIG.19




FIG.20





FIG.21

Silicon on oxide



Surface structure







FIG.22



10094228 122601

FIG.23

